RICHMOND METROPOLITAN TRANSPORTATION AUTHORITY

RICHMOND EXPRESSWAY SYSTEM

CONTRACT NO. MR – 2023

ADDENDUM NO. 1

May 23, 2023 DESCRIPTION

The attached pages are issued to amend and become part of the Contract Documents.

Contractor shall acknowledge receipt of this Addendum on the Receipt of Addenda form (Contract Page RA-1). Failure to complete and include the RA-1 form in the bid package may cause bid to be found irregular.

There is no change in the date that bids are due, and no change in the contract completion date from the dates contained in the Invitation to Bid.

Invitation To Bid

All Bidders are directed to replace Page IB-1 from the Bid Documents with Addendum No. 1 Page IB-1.

This Addendum has been issued to indicate units for Bridge Repairs will be EACH.

Bid for General Construction Contract

All Bidders are directed to replace Pages P-3 and P-4 from the Bid Documents with Addendum No. 1 Pages P-3 and P-4. This Addendum has been issued to add line item (30) for "BRIDGE 68, POTENTIAL CRACK ARREST "to the Bid Tab and to delete items for Superpave Asphalt SM 9.5E (76-22) and Flexible Pave. Planing (1.5" Depth).

Special Provision Table of Contents

All Bidders are directed to replace Page SP-ii from the Bid Documents with Addendum No. 1 Page SP-ii. This Addendum has been issued to indicate Asphalt Concrete Overlay is no longer in contract (N.I.C)

Special Provision Bridge Repairs

All Bidders are directed to replace Page SP-I-4 from the Bid Documents with Addendum No. 1 Page SP-I-4. This Addendum has been issued to indicate that units for Bridge Repairs will be EACH and to add line for "BRIDGE 68, POTENTIAL CRACK ARREST".

Special Provision Asphalt Concrete Overlay

All Bidders are directed to delete SP-T, Asphalt Concrete Overlay. This item is no longer in contract. (N.I.C)

Appendix

All Bidders are directed to insert "Bridge Elevation" drawings (73 pages) from bridge inspections showing approximate locations of proposed shotcrete repairs at the end of the Appendix. It is noted that locations of the repairs and size are approximate and may vary based on field conditions at the time of repair. It is also noted that particular attention should be paid to the legend on each sheet, as existing patches are also shown and do not require repairs.

RICHMOND METROPOLITAN TRANSPORTATION AUTHORITY

RICHMOND EXPRESSWAY SYSTEM

CONTRACT NO. MR-2023

MISCELLANEOUS REPAIRS

INVITATION TO BID

The Richmond Metropolitan Transportation Authority (RMTA), 901 East Byrd Street, Suite 1120, Richmond, Virginia 23219 until 10:00 a.m. local time, will receive sealed Proposals for the above project on Wednesday, June 14, 2023.

Sealed bid documents will be transferred by RMTA staff to the Powhite South-Administration Building, located at 6500 Powhite Parkway, Richmond, VA 23225 where the bids will be publicly opened and read at 11:00 a.m. local time. All Virginia executive orders, and CDC guidance related to COVID-19 must be adhered to at all times while on the RMTA premises.

The work under this contract shall be completed no later than May 31, 2024.

The principal items of work and approximate quantities are as follows:

<u>Item:</u>	Quantity:	Unit:
Shotcrete, (Standard)	52	S.F.
Shotcrete, (Elevated)	353	S.F.
Shotcrete, (Over Water)	1174	S.F.
Bridge 9N, Floorbeam 30, Remove Laminar Defect	1	EA.
Bridge 10S, East Abutment, NE Bearing, Remove and Replace	e 1	EA.
Bearing Sole Plate Weld		
Bridge 63, Span 17, Girder 6, Remove Small Welded Attachn	nent 1	EA.
Bridge 63, Pier 22, Unit 23 Girder 1 Bearing Realignment	1	EA.
Bridge 64, Pier 5, Unit 5, Girder 4 & Pier 7, Unit 7, Girder 4,	1	EA.
Remove and Repair Bearing Sole Plate Weld		
Bridge 65, Pier 16, Unit 16, Girder 1 and Pier 19, Girder 4,	1	EA.
Unit 20, Remove and Replace Bearing Sole Plate		
Bridge 68, Pier 19, Unit 2, G1-G3 and Pier 3, Unit 6, G1-G4	1	EA.
Bearing Realignment		
Repair Asphalt Concrete Pavement Cracks	50,000	L.F.
Debris Removal – James River Bridge (Rt. 76)	1	L.S.

RMTA MR-2023 Bid Tab

) (INSERT BIDDER FIRM NAME HERE)
--	----------------------------------

ITEM						2020
NO.	ITEM DESCRIPTION	UNIT	QUANTITY	UNIT PRICE	AMOUNT	SPECIFICATION
	BRIDGE 63, SPAN 17, GIRDER 6, REMOVE SMALL WELDED					
25	ATTACHMENT	EA	1			SP-I
	BRIDGE 63, PIER 22, UNIT 23 GIRDER 1 BEARING					
26	REALIGNMENT	EA	1			SP-I
	BRIDGE 64, PIER 5, UNIT 5, GIRDER 4 & PIER 7, UNIT 7, GIRDER 4, REMOVE AND REPAIR BEARING SOLE PLATE					
27	WELD	EA	2			SP-I
	BRIDGE 65, PIER 16, UNIT 16, GIRDER 1 AND PIER 19,		_			9. .
	GIRDER 4, UNIT 20, REMOVE AND REPLACE BEARING SOLE					
28	PLATE WELD	EA	2			SP-I
	BRIDGE 68, PIER 19, UNIT 2, G1-G3 AND PIER 3, UNIT 6, G1-					
29	G4 BEARING REALIGNMENT	EA	7			SP-I
30	BRIDGE 68, POTENTIAL CRACK ARREST	EA	1			SP-I
31	BRIDGE 9N, FLOORBEAM 30, REMOVE LAMINAR DEFECT	EA	1			SP-I
	BRIDGE 10S, EAST ABUTMENT, NE BEARING, REMOVE AND					
32	REPLACE BEARING SOLE PLATE WELD	EA	1			SP-I
33	TOPSOIL, CLASS B	CY	30			244/602
34	REGULAR SEED	LB	100			244/603
35	FERTILIZER (15-30-15)	TON	1			244/603
36	LIME	TON	1			244/603
37	CONCRETE COATING	SF	52			SP-R
38	CLEAN MANHOLE	EA	1			ATTD/SP-H
39	TYPE A PAVEMENT LINE MARKING 6"	LF	9800			704/SP-P
40	TYPE A PAVEMENT LINE MARKING 12"	LF	2800			704/SP-P
41	TYPE B CLASS VI PAVEMENT LINE MARKING 6"	LF	1070			704/SP-P
42	TYPE B CLASS VI PAVEMENT LINE MARKING 12"	LF	450			704/SP-P
43	PAVEMENT MESSAGE MARK "E-ZPass"	EA	3			704/SP-P
44	PAVEMENT MESSAGE MARK "ONLY"	EA	3			704/SP-P

RMTA MR-2023 Bid Tab

ITEM						2020
NO.	ITEM DESCRIPTION	UNIT	QUANTITY	UNIT PRICE	AMOUNT	SPECIFICATION
45	CRUSHED AGGREGATE NO. 21A OR 21B	TON	5			208
46	COARSE AGGREGATE NO.57	TON	5			203
47	AGGREGATE MATERIAL NO.1	TON	5			203
48	DRY RIPRAP CLASS I	TON	5			204
49	FLOWABLE BACKFILL	CY	3			509/SP-J
50	DEBRIS REMOVAL AT THE JAMES RIVER BRIDGE	LS	1			SP-K
51	DRAINAGE STRUCTURE REPAIRS	EA	5			SP-Q
52	RAILWAY COORDINATION SERVICE, BRIDGE 8	LS	1			107.19/SP-U

(SIGN HERE)	(INSERT
Signature of Owner, Partner, or Corporate Officer:	Title:
	TOTAL:

CONTENTS

XVII.	DRAINAGE STRUCTURE REPAIRS	SP-Q
XVIII.	CONCRETE COATING	SP-R
XIX.	CONCRETE SIDEWALK	SP-S
XX.	ASPHALT CONCRETE OVERLAY (N.I.C)	<u>SP-T</u>
XXI.	ASPHALT MATERIAL PRICE ADJUSTMENT	SP-U
XXII.	CONSTRUCTION AGREEMENT (CSX Railroad Agreement)	SP-V
XXIII.	APPENDIX (provided under a separate cover)	SP-Y

Measurement and Payment


The pay items for the repairs will be paid for at the contract bid price at each location of bridge steel repairs. This price shall include all materials, labor, tools, equipment, and incidentals necessary to complete the repairs including access to the site, jacking and shoring procedures, removal of existing steel, steel fabrication, cutting, grinding, steel installation, welding, labor, shop and field cleaning, priming and painting, ultrasonic testing (where noted on plans), and shop coating of steel plates.


This price shall also include review fees; submittals; and preparation of all plans, drawings, schedules, and narratives necessary for describing the Contractor's means and methods required to perform the work. This price shall include any requirements to remain in compliance with all environmental laws and regulations for work near or in the James River and Kanawha Canal. Legal offsite disposal of all waste materials shall be incidental to this item.


Any repairs which may require coordination with railroads shall be performed in accordance with the Supplemental Specifications, Section 107.19 Railway-Highway Provisions.


Payment will be made under:


ITEM NO.	ITEM DESCRIPTION	UNIT	QUANTITY	UNIT PRICE	AMOUNT	SPECIFICATION
	BRIDGE 63, SPAN 17, GIRDER 6, REMOVE SMALL WELDED					
1	ATTACHMENT	EA	1			
	BRIDGE 63, PIER 22, UNIT 23, GIRDER 1, BEARING REALIGNMENT					
2		EA	1			
	BRIDGE 64, PIER 5, UNIT 5, GIRDER 4, AND PIER 7, UNIT 7, GIRDER 4,					
3	REMOVE AND REPLACE BEARING SOLE PLATE WELD	EA	2			
	BRIDGE 65, PIER 16, UNIT 16, GIRDER 1 AND PIER 19, GIRDER 4, UNIT					
4	20, REMOVE AND REPLACE BEARING SOLE PLATE WELD	EA	2			
	BRIDGE 68, PIER 19, UNIT 2, G1-G3 AND PIER 3, UNIT 6, G1-G4					
5	BEARING REALIGNMENT	EA	7			
	BRIDGE 68, PIER 2, POTENTIAL CRACK ARREST					
6		EA	1			
	BRIDGE 9N, FLOORBEAM 30, REMOVE LAMINAR DEFECT					
7		EA	1			
	BRIDGE 10S, EAST ABUTMENT, NE BEARING, REMOVE AND REPLACE					
8	BEARING SOLE PLATE WELD	EA	1			


















































































TOTAL

6 SF -

7 SF -

DENOTES CRACK

DENOTES DELAM


DENOTES SPALL


DENOTES PATCHING


DENOTES SCALING/ABRASION

RX EXPOSED REINFORCING

TOTAL PIER APPROXIMATE DETERIORATED AREA - 6 SF







SOUTH FACE ELEVATION (LOOKING NORTH)

WEST END VIEW (LOOKING EAST)

HNTB


2900 South Quincy Street, Suite 200 Arlington, VA 22206 (703) 824-5100 $R_{
m ichmond} M_{
m etropolitan} T_{
m ransportation} A_{
m uthority}$

BOULEVARD BRIDGE PLAN AND ELEVATION PIER 12

Sheet: 5 of 26

REVISIONS

© 2015, Commonwealth of Virginia





TOTAL


DENOTES CRACK
DENOTES DELAM
DENOTES SPALL

1 SF -28 SF -

DENOTES PATCHING
DENOTES SCALING/ABRASION


I SF - RX EXPOSED REINFORCING

TOTAL PIER APPROXIMATE DETERIORATED AREA - 2 SF




EAST END VIEW NORTH FACE ELEVATION (LOOKING WEST) (LOOKING SOUTH)

NOTE: CRACK SEALED WITH EPOXY



SOUTH FACE ELEVATION (LOOKING NORTH)



WEST END VIEW (LOOKING EAST)

HNTB

2900 South Quincy Street, Suite 200 Arlington, VA 22206 (703) 824-5100 $R_{
m ichmond} M_{
m etropolitan} T_{
m ransportation} A_{
m uthority}$

BOULEVARD BRIDGE PLAN AND ELEVATION PIER 14


N. T. S. Date: 9/2

Contract No.:

7 of 26

REVISIONS


© 2015, Commonwealth of Virginia






DENOTES CRACK
DENOTES DELAM
DENOTES SPALL
40 SF - DENOTES PATCHING
DENOTES SCALING/ABRASION
RX EXPOSED REINFORCING

TOTAL PIER APPROXIMATE
DETERIORATED AREA - 6 SF




EAST END VIEW (LOOKING WEST)

NORTH FACE ELEVATION (LOOKING SOUTH)



SOUTH FACE ELEVATION (LOOKING NORTH)



WEST END VIEW (LOOKING EAST)

HNTB

2900 South Quincy Street, Suite 200 Arlington, VA 22206 (703) 824-5100 $R_{
m ichmond} M_{
m etropolitan} T_{
m ransportation} A_{
m uthority}$


BOULEVARD BRIDGE PLAN AND ELEVATION PIER 15

Scale: Date: 9/202

Contract No.:

8 of 26


REV IS IONS







DENOTES CRACK
DENOTES DELAM
DENOTES SPALL
42 SF - DENOTES PATCHING
DENOTES SCALING/ABRASION
RX EXPOSED REINFORCING

TOTAL PIER APPROXIMATE DETERIORATED AREA - 5 SF



REVISIONS





SOUTH FACE ELEVATION (LOOKING NORTH)

WEST END VIEW (LOOKING EAST)

HNTB

2900 South Quincy Street, Suite 200 Arlington, VA 22206 (703) 824-5100

Richmond Metropolitan Transportation Authority

ļ

BOULEVARD BRIDGE PLAN AND ELEVATION PIER 16

Scale: Date

Contract N

Sheet: 9 of 26




FIGURE 10 LEGEND

TOTAL

DENOTES CRACK

I SF - DENOTES DELAM


DENOTES SPALL


46 SF - DENOTES PATCHING
DENOTES SCALING/ABRASION


I SF - RX EXPOSED REINFORCING

TOTAL PIER APPROXIMATE DETERIORATED AREA - 2 SF

@ PIER







SOUTH FACE ELEVATION (LOOKING NORTH)

WEST END VIEW (LOOKING EAST)

HNTB


2900 South Quincy Street, Suite 200 Arlington, VA 22206 (703) 824-5100 $\boxed{R_{\rm ichmond}\,M_{\rm etropolitan}T_{\rm ransportation}A_{\rm uthority}}$

BOULEVARD BRIDGE PLAN AND ELEVATION PIER 17

Scale: Date: 9/202

Sheet: 10 of 26

REVISIONS






6 SF - DENOTES CRACK
DENOTES DELAM
DENOTES SPALL

16 SF - DENOTES PATCHING
DENOTES SCALING/ABRASION


Rx EXPOSED REINFORCING

TOTAL PIER APPROXIMATE
DETERIORATED AREA - 6 SF




EAST END VIEW (LOOKING WEST)

NORTH FACE ELEVATION (LOOKING SOUTH)



SOUTH FACE ELEVATION (LOOKING NORTH)



WEST END VIEW (LOOKING EAST)


HNTB


2900 South Quincy Street, Suite 200 Arlington, VA 22206 (703) 824-5100

 $R_{ichmond} M_{etropolitan} T_{ransportation} A_{uthority}$

PLAN AND ELEVATION
PIER 18

Date: Co N.T.S. 9/2021 REV IS IONS







DENOTES CRACK

J SF - DENOTES DELAM

DENOTES SPALL


DENOTES PATCH


15 SF - DENOTES PATCHING


DENOTES SCALING/ABRASION

Rx EXPOSED REINFORCING

TOTAL PIER APPROXIMATE DETERIORATED AREA - I SF







SOUTH FACE ELEVATION (LOOKING NORTH)

WEST END VIEW (LOOKING EAST)

Richmond Metropolitan Transportation Authority


HNTB


2900 South Quincy Street, Suite 200 Arlington, VA 22206 (703) 824-5100 BOULEVARD BRIDGE PLAN AND ELEVATION PIER 21


N.T.S. Date: 9/2021


tract No.: Sheet:

REVISIONS














EAST FACE ELEVATION
(LOOKING WEST)

DENOTES SPALL DENOTES HEAVY ABRASION DENOTES PATCH RX EXPOSED REINFORCING TOTAL PIER APPROXIMATE DETERIORATED AREA - 4 SF

TOTAL


4 SF -

FIGURE 4

LEGEND

→ DENOTES CRACK

DENOTES DELAM



NORTH END VIEW (LOOKING SOUTH)

 $R_{
m ichmond}\,M_{
m etropolitan}T_{
m ransportation}A_{
m uthority}$

HNTB

2900 South Quincy Street, Suite 200 Arlington, VA 22206 (703) 824-5100 BRIDGE 63
PLAN AND ELEVATION
PIER 15

N.T.S. | Date: | Cont

No.: Sheet: 4 of 18






EAST FACE ELEVATION (LOOKING WEST)

FIGURE 10

TOTAL

DENOTES CRACK
DENOTES DELAM
DENOTES SPALL
DENOTES HEAVY ABRASION
DENOTES PATCH
RX EXPOSED REINFORCING
TOTAL PIER APPROXIMATE

DETERIORATED AREA - 32 SF



 $R_{\rm ichmond}\,M_{\rm etropolitan}T_{\rm ransportation}A_{\rm uthority}$

HNTB


2900 South Quincy Street, Suite 200 Arilington, VA 22206 (703) 824-5100 BRIDGE 63
PLAN AND ELEVATION
PIER 18

N.T.S. | Date: | Contract No.: | 5

10 of 18


REVISIONS





TOTAL DENOTES CRACK DENOTES DELAM DENOTES SPALL DENOTES HEAVY ABRASION DENOTES PATCH RX EXPOSED REINFORCING TOTAL PIER APPROXIMATE DETERIORATED AREA - 6 SF

FIGURE I I



 $\mathbf{R}_{\text{channel}}\mathbf{M}_{\text{constant}}\mathbf{T}_{\text{constant}}$

 $R_{
m ichmond} M_{
m etropolitan} T_{
m ransportation} A_{
m uthority}$

11 of 18

HNTB

2900 South Quincy Street, Suite 200 Arilington, VA 22206 (703) 824-5100 BRIDGE 63 PLAN AND ELEVATION PIER 19

Date: Contract No.: N.T.S. 10/2022

REVISIONS






FIGURE 12

TOTAL

LEGEND

DENOTES CRACK

DENOTES DELAM

DENOTES SPALL


DENOTES HEAVY ABRASION

DENOTES PATCH

RX EXPOSED REINFORCING

TOTAL PIER APPROXIMATE

DETERIORATED AREA - 6 SF



 $R_{
m ichmond}\,M_{
m etropolitan}T_{
m ransportation}A_{
m uthority}$

HNTB

2900 South Quincy Street, Suite 200 Arlington, VA 22206 (703) 824-5100 BRIDGE 63 PLAN AND ELEVATION PIER 19

N.T.S. | Date: | Contract | Contr

Contract No.: Sheet: 12 of 18









FIGURE 14









 $R_{
m ichmond} M_{
m etropolitan} T_{
m ransportation} A_{
m uthority}$


2900 South Quincy Street, Suite 200 Arilington, VA 22206 (703) 824-5100

BRIDGE 63 PLAN AND ELEVATION PIER 20

Jates 10/2022 14 of 18









LEGEND TOTAL → DENOTES CRACK 15 SF -DENOTES DELAM DENOTES SPALL DENOTES HEAVY ABRASION DENOTES PATCH R× EXPOSED REINFORCING


> TOTAL PIER APPROXIMATE DETERIORATED AREA - 15 SF




NORTH FACE ELEVATION (LOOKING SOUTH)

REVISIONS







SOUTH FACE ELEVATION (LOOKING NORTH)

EAST END VIEW (LOOKING WEST)


2900 South Quincy Street, Suite 200 Arilington, VA 22206 (703) 824-5100


BRIDGE 64 PLAN AND ELEVATION PIER 13W


2 OF 15


m Richmond m Metropolitanm Transportation m Authority


12/2022 N.T.S.































FIGURE 6

TOTAL

DENOTES CRACK
DENOTES DELAM
DENOTES SPALL
DENOTES HEAVY ABRASION
DENOTES PATCH
EXPOSED REINFORCING

TOTAL PIER APPROXIMATE DETERIORATED AREA - 4 SF





EAST FACE ELEVATION (LOOKING WEST)

REVISIONS

 $R_{
m ichmond}\,M_{
m etropolitan}T_{
m ransportation}A_{
m uthority}$

HNTB


2900 South Quincy Street, Suite 200 Arlington, VA 22206 (703) 824-5100 BRIDGE 66
PLAN AND ELEVATION
PIER 3

© 2014, Commonwealth of Virginia

.S. | Date: | Contr

6 of 44

FIGURE 8 LEGEND TOTAL → DENOTES CRACK 4 SF - DENOTES DELAM DENOTES SPALL DENOTES HEAVY ABRASION DENOTES PATCH Rx EXPOSED REINFORCING TOTAL PIER APPROXIMATE DETERIORATED AREA - 4 SF © PIER © PIER 4 ₩ WANTE IN AND IN NORTH END VIEW (LOOKING SOUTH) NAME. EAST FACE ELEVATION (LOOKING WEST) $R_{ m ichmond} M_{ m etropolitan} T_{ m ransportation} A_{ m uthority}$ BRIDGE 66 PLAN AND ELEVATION PIER 4 2900 South Quincy Street, Suite 200 Arilington, VA 22206 (703) 824-5100 10/2022 REVISIONS © 2014, Commonwealth of Virginia 8 of 44







REVISIONS

FIGURE 12

LEGEND TOTAL → DENOTES CRACK 10 SF - ₩₩ DENOTES DELAM DENOTES SPALL DENOTES HEAVY ABRASION 35 SF -DENOTES PATCH Rx EXPOSED REINFORCING TOTAL PIER APPROXIMATE

DETERIORATED AREA - 10 SF





EAST FACE ELEVATION (LOOKING WEST)

 $R_{
m ichmond} M_{
m etropolitan} T_{
m ransportation} A_{
m uthority}$



2900 South Quincy Street, Suite 200 Arilington, VA 22206 (703) 824-5100

BRIDGE 66 PLAN AND ELEVATION PIER 6

0ate: 10/2022 N.T.S.


12 of 44




FIGURE 14

LEGEND TOTAL → DENOTES CRACK 6 SF - DENOTES DELAM DENOTES SPALL DENOTES HEAVY ABRASION 24 SF -DENOTES PATCH Rx EXPOSED REINFORCING TOTAL PIER APPROXIMATE

DETERIORATED AREA - 6 SF





NORTH END VIEW (LOOKING SOUTH)

 $R_{
m ichmond} M_{
m etropolitan} T_{
m ransportation} A_{
m uthority}$

2900 South Quincy Street, Suite 200 Arilington, VA 22206 (703) 824-5100

BRIDGE 66 PLAN AND ELEVATION PIER 7

10/2022

14 of 44

REVISIONS





FIGURE 18 LEGEND TOTAL → DENOTES CRACK 7 SF - DENOTES DELAM DENOTES SPALL DENOTES HEAVY ABRASION 24 SF -DENOTES PATCH Rx EXPOSED REINFORCING TOTAL PIER APPROXIMATE © PIER © PIER DETERIORATED AREA - 7 SF 14 **AIIAII** NORTH END VIEW (LOOKING SOUTH) 311411 ALENIE . EAST FACE ELEVATION (LOOKING WEST) $R_{ m ichmond} M_{ m etropolitan} T_{ m ransportation} A_{ m uthority}$ BRIDGE 66 PLAN AND ELEVATION PIER 9 2900 South Quincy Street, Suite 200 Arilington, VA 22206 (703) 824-5100 Jates 10/2022 REVISIONS © 2014, Commonwealth of Virginia 18 of 44






REVISIONS

FIGURE 20

LEGEND TOTAL → DENOTES CRACK IO SF - ₩₩ DENOTES DELAM DENOTES SPALL DENOTES HEAVY ABRASION 45 SF -DENOTES PATCH © PIER Rx EXPOSED REINFORCING TOTAL PIER APPROXIMATE DETERIORATED AREA - 10 SF



EAST FACE ELEVATION (LOOKING WEST)


2900 South Quincy Street, Suite 200 Arilington, VA 22206 (703) 824-5100


 $R_{
m ichmond} M_{
m etropolitan} T_{
m ransportation} A_{
m uthority}$


BRIDGE 66 PLAN AND ELEVATION PIER 10

10/2022 N.T.S.

20 of 44







-©_

€ PIER


APPROX. GROUND LINE

FIGURE 8

TOTAL

DENOTES CRACK
DENOTES DELAM
DENOTES SPALL
DENOTES HEAVY ABRASION
DENOTES PATCH
RX EXPOSED REINFORCING
TOTAL PIER APPROXIMATE

DETERIORATED AREA - 3 SF



NORTH FACE ELEVATION (LOOKING SOUTH)


 $R_{
m ichmond}\,M_{
m etropolitan}T_{
m ransportation}A_{
m uthority}$

HNTB

2900 South Quincy Street, Suite 200 Arilington, VA 22206 (703) 824-5100 BRIDGE 67 PLAN AND ELEVATION PIER 4

8 OF 22

e: Date: Contract No.
N.T.S. 10/2022



WEST END VIEW (LOOKING EAST)

